

Liberty Bridge Detour Alternate Route for Ramp to US 19 / SR 51 Liberty Bridge (Ramp B)

1. Begin Detour at (or Prior to) the Intersection of Boulevard of the Allies and Grant Street.
2. For Detour Access from the West, North, or East:
   Follow Grant Street Southbound to the I-376 Westbound Access Ramp near the Ft Pitt Blvd. / Grant Street Intersection.
3. For Detour Access from the South:
   Turn Left onto Boulevard of the Allies, then Left onto Stanwix Street to the I-376 Westbound Access Ramp near the Ft Pitt Boulevard / Stanwix Street Intersection.
4. For Detour Access from Smithfield Street:
   Turn Left onto Ft Pitt Boulevard to the I-376 Westbound Access Ramp near the Ft Pitt Boulevard / Stanwix Street Intersection.
5. Follow I-376 Westbound across the Ft Pitt Bridge and through the Ft Pitt Tunnel.
6. Take Exit 69A toward South US 19 / Banksville Road.
7. Keep Left and loop back to I-376 Eastbound toward South Truck US 19 / to South SR 51.
8. Follow I-376 Eastbound and take Exit 69B toward South Truck US 19 / South SR 51Uniontown.
9. Merge onto and follow South SR 51.
10. For Detour Access to South Truck US 19 (Toward Dormont):
    Follow South SR 51 toward Warrington Avenue, then Exit right to South Truck SR 19 / Dormont, then end detour at West Liberty Avenue.
11. For Detour Access to South SR 51 (Toward Uniontown):
    Continue on South SR 51 and end detour beyond the interchange area for SR 51 / US 19 / West Liberty Avenue.